

[Print this page](#)

New Calibration Requirement from General Motors

Posted on May 18, 2017

There is new information available when it comes to windshield replacement on General Motors (GM) vehicles. In the past, forward facing camera calibration was not required when replacing the windshield.

GM has changed the calibration requirement of the forward facing camera, which GM refers to as the "frontview camera module". The new requirement for the entire GM vehicle line is to calibrate the forward facing camera.

- the windshield is replaced or R&I
- the camera bracket is replaced or R&I
- the FCM is replaced
- if directed to by a service bulletin

This new requirement can be found in the vehicle-specific **Control Module References** under **Front View Camera Module Programming and Setup**. The OEM Calibration Requirements Search and the OEM Glass Replacement matrix have been updated to reflect this change.

For more information on GM vehicle, check out the following OEM Information pages:

[Buick \(/oem-information/buick.html\)](#)

[Cadillac \(/oem-information/cadillac.html\)](#)

[Chevrolet \(/oem-information/chevrolet.html\)](#)

[GMC \(/oem-information/gmc.html\)](#)

